

Video Systems

Zhang Jiang, SH, China

Software-HDCS WIN

Release Notes

This document contains proprietary information of Honeywell International Inc. Information contained herein is to be used solely for the purpose submitted, and no part of this document or its contents shall be reproduced, published or disclosed to a third party without the express permission of Honeywell International Inc.

Modification History

Version No.	Date <mm/dd/yy>	Changes made	Author	Reviewers	Documents Affected
1.0	06/17/2020				
1.0	07/03/2020				
1.0	08/13/2020				
1.0	09/15/2020				
1.0	12/01/2020				
1.0	12/09/2020				
1.0	12/17/2020				
1.0	04/12/2021				

Contents

1. Software Release Document	4
Release Notes.....	4
Software Build Time	Error! Bookmark not defined.
Software Version Information	Error! Bookmark not defined.
Supported Device List	Error! Bookmark not defined.
What's New and Fixed Issue List.....	4
Un-implemented Features or Functions.....	4
Test Report	6



1. Software Release Document

Release Notes

Product Name:	HDCS_Win
Version Number:	V7.0.R.210412
Date:	2021-04-12
File name:	Honeywell_HDCS-Win64_ChngEng_IS_V7.0.R.210412
MD5	984902747B505408399AF52EDD1A6162

What's New and Fixed Issue List

Date: 2021-04-12

Version: V7.0

No.	Modification information	type
1	Remove face attribute information	Fix
2	Change camera resolution property to number	Fix
3	Remove the DH information in DDNS	Fix
4	Remove admin right when install an run HDCS	New

Date: 2020-12-17

Version: V7.0

No.	Modification information	type
1	Allowed the MAC address 004084 login when add device.	Fix

Date: 2020-12-09

Version: V7.0

No.	Modification information	type
1	Optimize login logic for TUTK P2P	Fix

Date: 2020-12-01

Version: V7.0

No.	Modification information	type
1	Fix the TUTK P2P issue that edit UID does not work.	Fix
2	Add 256dev or 2000ch	New
3	Add the HDCS icon in installation folder	New
4	Remove redundant events in event config page	New

Date: 2020-09-15

Version: V7.0

No.	Modification information	type
1	Add remarks in log when export video clip.	New
2	Optimize UI.	New
3	Optimize French strings	Fix

Date: 2020-08-13

Version: V7.0

No.	Modification information	type
1	Support video export compression and encryption	New
2	Support multi-channel simultaneous download clip	New
3	Fix the video wall UI issue	Fix
4	Remove channel code in device export page.	Fix
5	Optimize TUTK connection	Fix
6	Add the border of the Task edit window	Fix
7	Fix the bug that refresh button not be showed in playback page	Fix

Date: 2020-07-03

Version: V6.0

No.	Modification information	type
1	Support TUTK P2P	New feature
2	Remove the link to web button in device config page when P2P connected.	Fix
3	Add checkbox in some pages, such as motion event.	Fix
4	Fix the language settings	Fix

Date: 2020-06-17

Version: V6.0

No.	Modification information	type
1	Support win 64bit	New feature
2.	Support modify the security questions in user menu page	New feature
3	Support H30 series fisheye dewarping in live view page	New feature
4	Change to "M" in the FTP FileSize parameter	Fixed
5	Fix DH P2P CS issue CVE-2020-9503	Fixed
6.	Fix the issue that the 9-16ch analog signal freezes in liveview when docking with HRHT.	Fixed

7	Fix the losing configuration issue when power off the PC	Fixed
---	--	-------

Un-implemented Features or Functions